


Rafael A. Gonzalez Soto, P.E.  
255 Giralda Ave 5<sup>th</sup> floor  
Coral Gables, Florida  
PE #83104  
(833) 888 3644  
admin@engipartners.com



**Owner:** TANVIR IMAN  
**Address:** 6505 NW 74 DR  
**Permit #:** SOLR2104-0144

To: City of Parkland Building Department

Subject: Solar Installation Roof Inspection

Madam/Sir: To whom it may concern,


I certify that the existing roof can support the load of the proposed solar system. The inspection verified that the roof installation is in compliance with the drawing details submitted with the permit application, and the Florida Building Code.

During the solar installation, the inspection will consist of verifying:

- Framing installation of 5/16" x 4" lag bolts through the base mount, sheathing and into center of trusses.
- Application of sealant around the base mounts.

I have completed inspection and verified the installation was completed per plans and installed per specs and our lags hit every rafter.

Respectfully,



Rafael A. Gonzalez Soto, PE